

Operating Manual

Service Software

for CS flow / dew point sensors

FA300/ VA300/ DP300/ FA4XX / VA4XX

💑 Service Software CS flow / dew point sensors (V 4.20)	
Information Online values Version: DP5.1 Date: 09.05.2007 Serial no: 7501 Item no.: 6993021 Output 20.00 Output: ? 4 mA: -80.0 20.00 Hysterese: 20 % Activation: Off	
Off Display / Alarm Cal Temperature Start recording Print Hell Disconnect Analogue output Cal Humidity Flow Settings Properties Exit	p



Service Software for flow / dew point sensors

Introduction

This service software can be used to check and change sensor settings on all CS flow and dew point sensors. For this purpose the sensors have to be connected to a PC via the service kit. The service kit consists of following components:

- Interface converter SDI / USB
- Power supply
- Appropriate cable set for sensor
- CD with service software and CS-Soft

Beside sensor settings the software also features online measurement with recording. For dew point sensors a recalibration function is available including a print out of calibration certificate.



Connect function

After starting the software, in order to communicate with the sensor device a connection has to be establishes in a first step. Please ensure that you have selected the correct COM-Port on your PC (see function "Properties").

Connection	
Connecting device	
Cancel	

By pressing the connect button at the main menu, a connection is created to the device. Upon successful connection, the main screen will carry sensor settings and information.

Service Software CS	flow / dew point s	ensors (V 4.20)			60
Information Version: I Date: 30: Serial no.: I Item no.: 720 Output g/m3 4 mA: -80.0 20 mA: 20.0	DP6.6 12.1899 .1 0050438 Pre alarm: Main alarm Hysterese: Activation:	Online values g/m2 % % % % % % % % % % % % %	3 Calibrat Humic Last 0 Numb	ion Settings dity Offset: 0.24 Cal. Date: 30.12.18 er of Cal.: 0	99
On Disconnect	Display / Alarm Analogue output	Cal Temperature Cal Humidity	Start recording	Print Properties	<u>H</u> elp Exit

Attention: Whenever a connection is established please use the disconnect function before removing the sensor from the service kit. Otherwise some important settings can be lost. In case the sensor has been disconnected without having used the "disconnect" function, please connect the sensor again and go to "Display / Alarm" and enable "auto transmit enable".



"On" functions

The "On" function is used to retrieve on line measurement data from the sensor. During on line measurement also the calibration functions and the measurement recording function are available.

nce Software CS flow / dew	point sensors (V 4.20)		
Information Version: DP6.6 Date: 30.12.1899 Serial no.: -1 Item no.: 720050438	Online values 2.4 g/m3 9.58 % 0.0 °F 17.18 mA		
Output: g/m3 Pr 4 mA: 90.0 M 20 mA: 20.0 H; Av	e alarm: 0.0 g/m3 ain alarm: 0.0 g/m3 psterese: 0.0 g/m3 ctivation: 0ff	Calibration Settings Humidity Offset: 0.24 Last Cal. Date: 30.12.189 Number of Cal.: 0	9
Off Display / Ala	m Cal Temperature Star	recording Print	Help

The online values are depending on the connected sensor type. There are always 4 values shown. The current value, is the calculated current at the 4-20 mA output of the sensor. By using a current meter this value can be measured on compared with the value shown on the online screen.



Cal Temperature, Cal Humidity

The software provides a dew point or humidity recalibration. (Temperature calibration is disabled in software version 4.20 and above).

The function is protected via a password. When using the calibration for the first time any password can be entered. Please remember this password for all future calibrations.

Attention:

Performing a dew point or humidity calibration is critical and following considerations showed be taken:

- Perform dew point calibrations at the working point. For example if you measure at around -40 °C_{td} do the calibration at that point.
- Do not perform calibration at too high dew points, as it will cause big errors at low dew points!
- We recommend calibration between -40 and -55 $^{\circ}C_{td}$.
- Use highly precise reference measuring instruments.
- Maintain conditioning time of about 1 hour minimum.

Calibrate humidity	×
Reference: Ctp	
UKCancel	



Start recording, recording data

During online measurement the recording function can be activated. This function will record measuring data into an Excel file.

Following settings are available:

- Recording interval between 1 second and several hours
- Filename: please don't enter any extension, it will be added automatically.
- A description is a free text.
- When selecting "Record average value" only the average values of the measuring interval is recorded. In other words an average value of the entire interval is stored in stead of the current value at a certain point of time.

Logging properties
hh mm ss Recording interval: 00 00 10
Filename: RecordFile .XLS
Description:
This is a text describing the measurement
Record average value
OK Cancel



Display/Alarm

Dew point sensors can monitor up to 2 alarms. The alarm threshold and hystersis are set in the alarm section of the window. Alarms are triggered whenever the measurement value is higher then the threshold value. Pre alarm is available for FA 300 series only.

Display / Alarm	X	Display / Alarm	
Alarm Pre alarm: g/m3 Main alarm: g/m3 Hysterese: g/m3 Hysterese: g/m3 Hysterese: g/m3 Hysterese: g/m3 Cancel	Display Humidity Temperature Analogue value: Abs. humidity [g/m3] ¥ Auto transmit active Temperature in Fahrenheit	Alarm Pre alarm: Main alarm: Hysterese: Alarm on dew point distant OK Cancel	Ce

A special alarm monitoring is implemented in the FA 4XX series, the so called "Alarm on dew point distance". It can be set on dew point only, and if enabled, the sensors will trigger an alarm, whenever the ambient temperature minus dew point temperature is smaller than the threshold setting. For example: if the dew point should be always 5 degrees below the ambient temperature a threshold value of 5 degrees has to be programmed.

These alarm monitoring can trigger a relay on connected accessories such as DS 301 or trigger an optical indication on DS 50 display.

The section display is important in case the sensor is connected to following instruments: DP 300, CS 2390, DS 50, DS 301. Following settings are recommended:

Humidity, Temperature, analogue value, auto transmit active
Flow sensor: velocity, auto transmit active
Dew point sensor: Humidity, Temperature, analogue value, auto
transmit active
Only one of the 3 possible values should be activated!
Only one of the 3 possible values should be activated!

In case the temperature values should be shown in Fahrenheit, please activate the corresponding tick box.



Analogue output

Please select the measurement value to be send out by the analogue output and the related scaling. Please enter line pressure for the physical parameter such as ppm[V] and the atmospheric dew point.

Analogue output	
Analogue output selection:	Scaling for analogue output:
Dewpoint Absolute humidity [g/m3]	4 mA: -80.0 °C td
Pressure:	1013 hPa
OK	Cancel

Analogue output	
Analogue output selection: Velocity Flow	Scaling for analogue output: 4 mA: 0.0 //min
c 🔄	20 mA: 2000.0 Vmin
Pressure:	hPa
OK	Cancel



Print

With this function calibration protocols can be printed and saved.

Print Window			
Description of probe: Order no.: Serial number:	FA 300-2 0699.3002 1649		Save to file
Measuring result: Reference value:	[°Ctd °Ctd	Load file
			Cancel



Properties

Please select interface (COM port) where the CS device is connected to and the printer port. The printer port is used to print calibration certificates.

Properties			
Interface port:	COM1 COM1 COM2 COM3 COM4		
Printer port:			1
0	ĸ	Cancel	

If you are not sure which COM port is the right one, please check the ports in the Device Manager of your PC. If the USB driver is installed correctly and the service kit is connected, you will find an entry "CS Instruments USB-SDI Interface" showing the assigned COM port.

a nevice wanager		
File Action View Help ← → 199 (27 28) (12 28) 😤 🗶		
EUKIS Computer Computer Solution Discinnes Divide Solution Solution Solution Solution Solution Solution Solution Divide Solution Solutio	Update Driver Disable Uninstal Scan for handware changes Prometties	

If you can not find this entry please repeat the driver installation. The detailed instruction is in the instruction manual delivered together with the service kit or can be downloaded from our server.



Flow settings

All settings of CS flow sensors can be changed in this dialog.

Customer standard:

Channel diameter: Temperature:	Please enter the correct channel diameter
Reference pressure:	CS flow sensors are calculating standard volumetric flow. This requires a reference pressure and temperature. For compressed air according to ISO 1217 the references are: 20 degree C temperature, 1000 hPa pressure.
Type of gas:	Select the corresponding gas type from the selection list. Please consider that some gases require a special calibration. We recommend to use air, O2 and N2 only.

Flow settings	
Customer standardChannel diameter:53.1mmTemperature:20.0CReference pressure:1000.0hPaType of gas:AirMaximum flow:601m3/h	Factory settings Velocity Filter grade: 5 Volume flow Profile factor: 0.812 Zero pressure: -1 Calculate 1 hour average value
Counter setting 484 OK Cancel	Flow unit C m3/h C l/minin C m3/min C l/s C cfm C kg/s Puls settings C 1 puls per m3 C 1 puls per 10 m3

Maximum flow:

Is read only and can not be changed. Depends on the flow sensor

Counter setting:CS flow sensors count the total consumption. The counter
can be set to any starting value.Flow unit:Please select the desired flow unitConsumption unit:Please select the desired unit for consumptionPulse setting:CS flow sensors feature a pulse output. This output can
send either one pulse per consumption unit or 1 pulse per
10 consumption units.

Other parameters are for service information and not accessible by users.



Contact:

Sales office South

Zindelsteiner Str. 15 D-78052 VS-Tannheim

Tel. +49 (0) 7705 97 89 9-0 Fax +49 (0) 7705 97 89 9-20

info@cs-instruments.com www.cs-instruments.com

Sales office North

Am Oxer 28c D-24955 Harrislee

Tel. +49 (0) 461 - 700 2025 Fax +49 (0) 461 - 700 2026

info@cs-instruments.com www.cs-instruments.com