CS Service Software

With the CS service software including the USB Modbus interface adapter, the FA 510 / FA 515 / FA 500 dew point sensors can be configured via laptop / PC. The following settings can be made via CS Service Software:

- Scaling of the 4...20 mA analogue output

- Assignment of the parameter to the analogue output (e.g. 4...20 mA = 0...10 g/m³)

- Available units: °Ctd, °Ftd, g/m³, mg/m³, ppmv/v, g/kg

- Reading out the firmware version, serial number, date of the last calibration

- One-point calibration (adjustment) of the sensors in the process. This requires a reference device

- Update of the sensor software (Firmware)

- Modbus settings as Modbus-ID, Baud rate, Stopbit, Parity

DESCRIPTION	ORDER NO.
CS Service Software incl. PC connection set, USB connection and interface adapter to the sensor	0554 2007