


## Drilling device with drill bit for installing a measurement point

Ideal for tapping under pressure. Using this special tapping device, a measuring point can be set up within a few minutes after welding on a threaded spigot and fitting a ball valve. As an alternative to welding on the spigot, a tapping clamp can be used.



Sample order code:

**0530 1208\_A1\_B1**

Drill holder	
A1	13 mm drill bit for 1/2" sensor shafts
A2	20 mm drill bit for 3/4" sensor shafts

Connection thread	
B1	G External thread
B2	NPT external thread

ACCESSORIES	ORDER NO.
<b>DRILL HOLDER:</b>	
Drill holder with G 1/2" External thread	Z530 1201
Drill holder with G 1" External thread	Z530 1202
Drill holder mit NPT 1/2" External thread	Z530 1203
Drill holder mit NPT 1" External thread	Z530 1204
<b>DRILL BIT:</b>	
13 mm drill bit for 1/2" sensor shafts	Z530 1205
20 mm drill bit for 3/4" sensor shafts	Z530 1206