DS 52 - LED process display

in wall housing for 0 (4)...20 mA standard signals



The DS 52 has 2 potential-free alarm contacts (changeover contacts) which can be charged with a maximum of 230 VAC, 3 A. The alarm thresholds are freely adjustable with the keys. The display is supplied with 230 VAC and has an internal mains unit which provides a voltage of 24 VDC/100 mA for the sensor.

Screwing clamps are available for forwarding the (0) 4...20 mA signal to superordinate controls.



Special features:

- Integrated in a well-designed wall housing
- Suitable for all common sensors . with 0 (4)...20 mA signal
- Easy operation •

Application example:

Pressure monitoring with optional alarm unit (buzzer + continuous light)

| Application example: | |
|-----------------------------|-------|
| Temperature monitoring with | alarm |

| Suitable for all common sensors with 0 (4)20 mA signal | | TECHNICAL DATA DS 52 | |
|---|-------------------------|-------------------------|---|
| | | Dimensions: | 4.6 x 5.2 x 3.6 mm |
| Easy operation | | | (WxHxD) |
| • 2 relay outputs (230 VAC, 3 A) | | Display: | LED, 5-digit, height 0.51, 2 LEDs for alarm |
| | | Keypad: | 4 keys: Enter, Back, Up, Down |
| | | Sensor input: | For sensors with 0 (4)20 m/ signal. Can be connected in 2-/3-/4-wire technology |
| DESCRIPTION | ORDER NO.: 0500 0009 | Accuracy: | Max. +/- 20 μΑ, typically +/- 10 μΑ |
| DS 52 LED process display in the wall housing | 0500 0009 | Burden: | 100 Ω |
| Options: | | Sensor supply: | 24 VDC, max. 100 mA |
| Power supply 24 VDC instead of 230 VAC | Z500 0001 | Power supply: (option): | 230 VAC, 50/60 Hz |
| Power supply 110 VAC instead of 230 VAC | Z500 0002 | | (24 VDC or 110 VAC) |
| Alarm unit mounted to the wall housing | Z500 0003 | Outputs: | 2 x relay output, changeover |
| Alarm unit for external mounting | Z500 0004 | | contact, 250 VAC, max. 3 A |
| | | Alarm thresholds: | Freely adjustable via keypad |
| Complete sets: | | Hysteresis: | Freely adjustable via keypad |
| DS 52 - all-in-one set for pressure monitoring/alerting, consisting of DS 52 LED display and pressure sensor 0232 psi | on request | Operating temperature: | 14…+140 °F (Storage temp.: -4176 °F) |
| DS 52 - all-in-one set for temperature monitoring/alerting, consisting of: DS 52 LED display and screw-in temperature sensor -58932 °F | on request | Control menu: | Can be locked via code for unauthorised access |